

CleanBlastPRO™ 1.2.0.484 – March 2022

What's New

- Updated Simplex and MPO factory profiles to optimize performance with new non-contact tips
- Ability to add, remove, and edit custom profiles via external software program and USB thumb drive
- Master User Code feature (prevents profile editing on-device)
- Support for longer tubing on FCLP-RCA-3 to enable users to perform auto-fill with handset mounted at the edge of a bench
- Simplified firmware update feature: hold dial at boot to initiate firmware update
- Ability to reset prime/clean counter
- Error message when attempting to fire/prime when the Fill-Valve is open
- Added warning for tilt detection and tightened tolerance on tilt error
- Added pre- and post-cleaning cycle options to profiles
- Improvements to Advanced Diagnostics, including:
 - Air filter clog detection warnings
 - Solenoid open-circuit detection warning
 - Fluid fault detection warnings
 - Contamination (water/improper solvent) detection
 - Fluid under/overconsumption
- Factory units pre-loaded with custom profiles
 - Duplex
 - ExtensionSimplex
 - ExtensionMPO

What's Fixed

- Minor bug fixes

Known Issues

- Prompt to import Master User Code during firmware update has image tearing on-screen when unit's language is Japanese.
- Prompt to insert thumb drive during firmware update has image tearing on-screen when unit's language is Korean.
- When error condition (red maintenance light) is present, no on-screen warning is given to indicate tank draining procedure is unavailable.